

<u>Photo #</u>	<u>Location Address:</u>	<u>Location Coordinates:</u>	<u>Damages:</u>
<u>1</u>	104 Moore St.	34.36849°N, 101.75371° W	Missing Lid
<u>2</u>	111 Moore St	34.36817° N, 101.75283° W	Bent Lid
<u>3</u>	214 Moore St	34.36671° N, 101.75386° W	Rusted Bottom
<u>4</u>	200-248 Paul Ave	34.36763° N, 101.75229° W	Bent Lid
<u>5</u>	106 Dudley Ave	34.36870° N, 101.75193° W	Broken Lid
<u>6</u>	310 Dudley Ave	34.36542° N, 101.75142°	Missing Lid & Rusted Bottom
<u>7</u>	307 Dudley Ave	34.36577° N, 101.75123° W	Missing Lid
<u>8</u>	105 Dudley Ave	34.36869° N, 101.75113°	Missing Lid & Rusted Bottom
<u>9</u>	203 W First St	34.36876° N, 101.75068 W	Rusted Bottom
<u>10</u>	104 Skipworth Ave	34.36842° N, 101.75063° W	Missing Lid & Rusted Bottom
<u>11</u>	203 Dudley Ave	34.36749° N, 101.75072° W	Missing Lid
<u>12</u>	705 Dudley Ave	34.36113° N, 101.75064°W	Rusted Bottom
<u>13</u>	501 Dudley Ave	34.36352° N, 101.75062° W	Rusted Bottom
<u>14</u>	404 Skipworth Ave	34.36486° N, 101.75060° W	Missing Lid & Rusted Bottom
<u>15</u>	113 Skipworth Ave	34.36785° N, 101.74956° W	Broken Lid & Rusted Bottom
<u>16</u>	7374 FM 145	34.36868° N, 101.76085° W	Rusted Bottom & Front Dented
<u>17</u>	613 Skipworth Ave	34.36162° N, 101.74934° W	Bent Lid
<u>18</u>	508 US 87 S	34.36354° N, 101.74812° W	Rusted Bottom
<u>19</u>	115 E Main St	34.36671 ° N, 101.74646° W	Missing Lid
<u>20</u>	500 US 87 S	34.36320° N, 101.74863° W	Rust Bottom & Broken Lid
<u>21</u>	310 Nicholson Ave	34.36565° N, 101.74690° W	Missing Lid
<u>22</u>	106 Nicholson Ave	34.36850° N, 101.74649° W	Rusted Bottom
<u>23</u>	115 E Main St	34.36656° N, 101.74665° W	Missing Lid & Rusted Bottom
<u>24</u>	200-260 Nicholson Ave	34.36722° N, 101.74630° W	Broken Lid & Rusted Bottom
<u>25</u>	US 87 N	34.36425° N, 101.74779° W	Bent Lid
<u>26</u>	311 Nicholson Ave	34.36532° N, 101.74571° W	Rusted Bottom
<u>27</u>	200 E Fifth St	34.36324° N, 101.74515° W	Missing Lid
<u>28</u>	405 Nicholson Ave	34.36476° N, 101.74613 W	Missing Lid
<u>29</u>	1000-1098 E Sixth St	34.36215° N, 101.74706° W	Missing Lid
<u>30</u>	401 E Main St	34.36669° N, 101.74346° W	Missing Lid
<u>31</u>	401 Ripley Ave	34.36501° N, 101.74411° W	Bent Lid & Rusted Bottom
<u>32</u>	311 Ripley Ave	34.36549° N, 101.74450° W	Broken Lid & Rusted Bottom
<u>33</u>	106 Ripley Ave	34.36866° N, 101.74543° W	Missing Lid
<u>34</u>	305 E Fourth St	34.36516° N, 101.74401° W	Bent Lid
<u>35</u>	106 Ripley Ave	34.36859° N, 101.74557° W	Missing Lid & Rusted Bottom
<u>36</u>	206 Ripley Ave	34.36728° N, 101.74542° W	Missing Lid
<u>37</u>	203 N Dunn Ave	34.36722° N, 101.74309° W	Rusted Bottom & Broken Lid

City of Kress Dumpsters

Locations & Damages

<u>38</u>	206 Caldwell Ave	34.36736° N, 101.74298° W	Rusted Bottom & Missing Lid
<u>39</u>	E Second St	34.36786° N, 101.74469° W	Bent Lid

City of Kress Dumpsters

Photos

1



2



3




4



5



6



7



8



9



10



11




City of Kress Dumpsters

Photos

12



13




14



15



16



17



18



19




20



21



22




23




24



25



26



27



City of Kress Dumpsters

Photos

28



29



30



31



32




33



34



35



37



38



39

